

WARNING: POSSIBLE CANCER HAZARD OR LUNG DAMAGE IF INHALED - MAY CAUSE ALLERGIC REACTION - MAY CONTAIN FLUORIDES.

PROTECT YOURSELF AND OTHERS - TAKE PRECAUTIONS WHEN WELDING -BEFORE USE. READ AND UNDERSTAND THIS INFORMATION, THE MANUFACTURER'S INSTRUCTIONS. MATERIAL SAFETY DATA SHEETS (MSDS), AND YOUR EMPLOYER'S SAFETY PRACTICES, WHICH SHOULD BE BASED ON THE SAFETY IN WELDING AND CUTTING (ANSI Z49.1), AND OSHA SAFETY AND HEALTH STANDARDS 29CFR1910.

FUMES AND GASES CAN BE HAZARDOUS TO YOUR HEALTH, SKIN SENSITIZATION, IRRITATION OF SKIN, EYE, AND RESPIRATORY TRACT, NEUROLOGICAL DAMAGE OR DEATH CAN RESULT FROM OVER-EXPOSURE. KEEP YOUR HEAD OUT OF THE FUME. USE VENTILATION, PREFERABLY LOCAL EXHAUST VENTILATION, ADEQUATE TO KEEP THE CONCENTRATION OF FUMES AND GASES BELOW THE EXPOSURE LIMITS, AWAY FROM YOUR BREATHING ZONE AND THE GENERAL AREA. SPECIAL ATTENTION TO VENTILATION IS REQUIRED IN CONFINED, SMALL OR CROWDED SPACES. IF ADEQUATE VENTILATION IS NOT AVAILABLE, WEAR APPROPRIATE RESPIRATORY PROTECTION. WASH SKIN AFTER CONTACT WITH DUST OR FUME.

ARC RAYS CAN INJURE EYE AND BURN SKIN. ELECTRIC SHOCK CAN KILL. DO NOT TOUCH LIVE ELECTRICAL PARTS, WEAR CORRECT EYE, EAR AND BODY PROTECTION.